

HURRICANE TEST LABORATORY, INC.

Windows • Doors • Store-Fronts • Curtain Walls • Shutters • EIFS • Metal Building Systems

STRUCTURAL TEST REPORT – WALL PANEL


Test Date: 08/13/98

Job Tracking #: 0168-0808-98

Specimen #: 2

Page #: 4

10.2 LOCATION OF DEFLECTION MEASUREMENTS:



DROJOs, Inc Green Building Systems
P.O Box 7238
West Palm Beach, FL 33405
Adam Rish

ENGINEER OF RECORD

Fredrick D. Shaffer, P.E.
FL Reg. # 26694